Approved For Release 2002/10/16: CIA-RDP72B00464R000400060056-5

21 September 1970

/2 cys. encl.

encl.

25X1

Subject:

Contract (657)-12846 Follow-On EMR

Monthly Technical Progress Report Period Ending 31 July 1970

Dear Burt:

In fulfillment of the subject obligation enclosed please find one (1) copy of this Contractor's report No. 78.

Regards. Jim

STATINTL

JM: vg Encl.

SPO

ASPO

cc:

FOR OFFICIAL USE ONLY Approved For Releaser 2000 WIN FEARBAND B00464R000400060056-5

3641-70

STATINTL

CONTRACTOR

MONTHLY LETTER REPORT
1940-L-78

STATINTL

CONTRACT: (657)-12846 25X1

REPORT PERIOD: AUGUST 1970

APPROVED BY

FOR OFFICIAL USE ONLY Approved For Release 12002/19/06/2014 RDP72B00464R000400060056-5

Only outstanding Contract Items are listed hereunder. NOTE: BASIC CONTRACTUAL OBLIGATIONS W/S Item V - Configuration Records Contractor's correspondence to SPO of 21 July 1970 submitted recommendations for disposition of records. Contracting Officer's letter of 4 August 1970 approved recommendations - Records will be STATINTL retained by Contractor until such time as they will provide no significant program benefit, at which time they will be destroyed. ITEM CONSIDERED CLOSED & WILL BE DELETED FROM SUBSEQUENT REPORT OPTIONAL REQUIREMENTS (Spare Parts) Remarks Nomenclature Qty. Pt. No. List No. Seq. No. 024600 542065-1 EDD 11/70 (*) Sense Card 1 4 Ass'y STATINTL (*) Under prior report | forwarded | | correspondence of TATINTL 25 June 1970 relating to problems being encountered in transistor selection and/or availability. STATINTL is pursuing two parallel courses. Adding capacitors to present modules to slow down transistor switching time. 2. Purchasing new transistors and selecting them to work in modules. is endeavoring to accomplish item I above as this means STATINTL that the present modules could be reworked and the 11/70 date

STATINTL

evaluating feasibility of repairing present module. STATINTL

If item 2 is the only feasible solution would have to completely rebuild the 13 Sense Amplifier modules used in the Sense Card Ass'y. as the present transistors cannot be removed and replaced (potted cordwood module). This would involve a whole new procurement cycle and EDD would be 6 - 8

**Appropriated For Release 2002/10RG VOIA ROP 72800464R000400060056-5

is enough room around outside of existing module to add capacitor. _____ module assembly vendor is presently

FOR OFFICIAL USE ONLY

Preliminary engineering investigation by

most likely met.

Page 1 of 1

STATINTL

|shows that there

UNCLASSIFIED Approved For Release 2002/10/16: CIA-RDP72B00464R000400060056-5

OSA -2640 - 70

21 September 1970

Subject:

Contract AF33(657)-12846 Follow-On EMR Program

Monthly Fiscal Report, Submittal of

Dear Burt:

Enclosed please find this Contractor's "Monthly Fiscal Report #77" for the period ending 30 August 1970.

Regards,

JM:vg Encl.

SPO

STATINTL

Jacker ay

FOR OFFICIAL USE ONLY, Approved For Release 2002/10016 WC1APROPURE MANAGEMENT OF A - 2640 - 70

STATINTL

FINANCIAL STATUS REPORT

CONTRACT: (F/O EMR)
(657)-1284625X1

REPORT PERIOD: August 1970

APPROVED